

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
AaA: Agar-----	90	Not limited		Not limited		Not limited	
AaB: Agar-----	90	Not limited		Not limited		Not limited	
AdC: Anselmo-----	60	Very limited Depth to bedrock	1.00	Very limited Seepage Depth to bedrock	1.00 0.42	Somewhat limited Seepage Depth to bedrock	0.50 0.42
Dunday-----	30	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
AhB: Anselmo-----	55	Very limited Depth to bedrock	1.00	Very limited Seepage Depth to bedrock	1.00 0.42	Somewhat limited Seepage Depth to bedrock	0.50 0.42
Holt-----	30	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Seepage	1.00 0.21
AhC: Anselmo-----	50	Very limited Depth to bedrock	1.00	Very limited Seepage Depth to bedrock	1.00 0.42	Somewhat limited Seepage Depth to bedrock	0.50 0.42
Holt-----	40	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Seepage	1.00 0.21
AtE: Anselmo-----	60	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 0.42	Very limited Slope Seepage Depth to bedrock	1.00 0.50 0.42
Tassel-----	30	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Slope	1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 0.50
BaE: Betts-----	85	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Bb: Bon-----	85	Very limited Depth to saturated zone Seepage Too clayey Flooding	1.00 1.00 0.50 0.40	Very limited Depth to saturated zone Seepage Flooding	1.00 1.00 0.40	Somewhat limited Too clayey Seepage	0.50 0.21
Bc: Bon-----	75	Very limited Flooding Depth to saturated zone Seepage Too clayey	1.00 1.00 1.00 0.50	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Somewhat limited Too clayey Seepage	0.50 0.21
BLD: Boro-----	50	Very limited Too clayey Slope	1.00 0.63	Somewhat limited Slope	0.63	Very limited Too clayey Slope	1.00 0.63
Lakoma-----	35	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.63	Very limited Depth to bedrock Slope	1.00 0.63	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.63
BmB: Boro-----	60	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Millboro-----	35	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
BmC: Boro-----	60	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Millboro-----	35	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
CaA: Carter-----	55	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Capa-----	35	Very limited Too clayey Sodium content	1.00 1.00	Not limited		Very limited Too clayey Sodium content	1.00 1.00

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
CbA: Carter-----	60	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Promise-----	35	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Cd: Cass-----	90	Very limited Flooding Seepage	1.00 1.00	Very limited Flooding Seepage	1.00 1.00	Somewhat limited Seepage	0.50
CrC: Coly-----	85	Not limited		Not limited		Not limited	
CrE: Coly-----	80	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
DaA: Dunday-----	90	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
Du: Durrstein-----	90	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Sodium content	1.00
		Sodium content	1.00			Too clayey	0.50
		Too clayey	0.50				
Fd: Fedora-----	90	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 0.50
Ha: Haynie Variant-----	55	Not limited		Not limited		Not limited	
Munjor-----	35	Very limited Seepage	1.00	Very limited Seepage	1.00	Somewhat limited Seepage	0.50

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
HoA: Holt-----	85	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Seepage	1.00 0.21
HoB: Holt-----	85	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Seepage	1.00 0.21
HoC: Holt-----	90	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Seepage	1.00 0.21
HoD: Holt-----	85	Very limited Depth to bedrock Slope	1.00 0.63	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.63	Very limited Depth to bedrock Slope Seepage	1.00 0.63 0.21
Ia: Inavale-----	90	Very limited Flooding Seepage Too Sandy	1.00 1.00 1.00	Very limited Flooding Seepage	1.00 1.00	Very limited Too Sandy Seepage	1.00 1.00
InB: Inavale-----	85	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
Ix: Norway-----	90	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too Sandy	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
		Too Sandy	1.00				
JaA: Jansen-----	85	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
JaB: Jansen-----	85	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
JaC: Jansen-----	90	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
JbA: Jansen-----	65	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
Brocksburg-----	25	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
Ko: Kolls-----	90	Very limited Depth to saturated zone Too clayey Ponding	1.00 1.00 1.00	Very limited Depth to saturated zone Ponding	1.00 1.00	Very limited Too clayey Depth to saturated zone Ponding	1.00 1.00 1.00
LaB: Labu-----	85	Very limited Depth to bedrock Too clayey	1.00 1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Too clayey	1.00 1.00
LaC: Labu-----	85	Very limited Depth to bedrock Too clayey	1.00 1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Too clayey	1.00 1.00
LaD: Labu-----	85	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.63	Very limited Depth to bedrock Slope	1.00 0.63	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.63
LcF: Labu-----	45	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Sansarc-----	40	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00
LoD: Lakoma-----	65	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.63	Very limited Depth to bedrock Slope	1.00 0.63	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.63
Okaton-----	35	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.63	Very limited Depth to bedrock Slope	1.00 0.63	Very limited Depth to bedrock Too clayey Slope	1.00 1.00 0.63
LwB: Lakoma-----	45	Very limited Depth to bedrock Too clayey	1.00 1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Too clayey	1.00 1.00
Wewela-----	30	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00
LwC: Lakoma-----	50	Very limited Depth to bedrock Too clayey	1.00 1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Too clayey	1.00 1.00
Wewela-----	30	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock	1.00
M-W: Miscellaneous Water Area-----	100	Not rated		Not rated		Not rated	
MaD: Mariaville-----	100	Very limited Depth to bedrock Slope	1.00 0.37	Very limited Depth to bedrock Slope	1.00 0.37	Very limited Depth to bedrock Slope	1.00 0.37
MaF: Mariaville-----	85	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
MdF: Mariaville-----	40	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00
Labu-----	25	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00
Anselmo-----	15	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Slope Seepage Depth to bedrock	1.00 1.00 0.42	Very limited Slope Seepage Depth to bedrock	1.00 0.50 0.42
MeC: Meadin-----	90	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage Gravel content	1.00 1.00 0.77
MeE: Meadin-----	75	Very limited Seepage Too Sandy Slope	1.00 1.00 1.00	Very limited Seepage Slope	1.00 1.00	Very limited Too Sandy Seepage Slope Gravel content	1.00 1.00 1.00 0.77
MoA: Millboro-----	90	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
MoB: Millboro-----	90	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
MoC: Millboro-----	90	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
MpB: Millboro-----	55	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Lakoma-----	35	Very limited Depth to bedrock Too clayey	1.00 1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Too clayey	1.00 1.00

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
MpC: Millboro-----	50	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
Lakoma-----	40	Very limited Depth to bedrock Too clayey	1.00 1.00	Very limited Depth to bedrock	1.00	Very limited Depth to bedrock Too clayey	1.00 1.00
Mr: Mosher-----	75	Very limited Depth to saturated zone Too Sandy Sodium content	1.00 1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Sodium content Too Sandy	1.00 0.50
Ms: Mosher-----	55	Very limited Depth to saturated zone Too Sandy Sodium content	1.00 1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Sodium content Too Sandy	1.00 0.50
Jerauld-----	30	Very limited Sodium content Too clayey	1.00 0.50	Not limited		Somewhat limited Too clayey	0.50
ObE: Okaton-----	65	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00
Lakoma-----	35	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00
OcF: Okaton-----	55	Very limited Slope Depth to bedrock Too clayey Content of large stones	1.00 1.00 1.00 0.56	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Too clayey Content of large stones	1.00 1.00 1.00 0.56
Mariaville-----	30	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope	1.00 1.00

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
OeC: O'Neill-----	90	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
On: Onita-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Or: Orthents, Loamy-----	70	Not rated		Not rated		Not rated	
Orthents, Shaly-----	30	Not rated		Not rated		Not rated	
Ot: Onita-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
Pg: Orthents, Gravelly--	100	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage Gravel content	1.00 1.00 0.68
Pm: Platte-----	85	Very limited Flooding Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Too Sandy Seepage Depth to saturated zone	1.00 1.00 1.00
PrA: Promise-----	90	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
PrB: Promise-----	90	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00
PrC: Promise-----	100	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
RaA: Ree-----	90	Very limited Seepage	1.00	Not limited		Not limited	
RaB: Ree-----	90	Very limited Seepage	1.00	Not limited		Not limited	
RaC: Ree-----	90	Very limited Seepage	1.00	Not limited		Not limited	
RbA: Ree-----	85	Very limited Seepage Too clayey	1.00 0.50	Not limited		Somewhat limited Too clayey	0.50
RcC: Ree-----	70	Very limited Seepage	1.00	Not limited		Not limited	
Tassel-----	20	Very limited Depth to bedrock	1.00	Not limited		Very limited Depth to bedrock Seepage	1.00 0.50
ReA: Reliance-----	85	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
ReB: Reliance-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
ReB2: Reliance-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
ReC: Reliance-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
ReC2: Reliance-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
ReD: Reliance-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
ReD2: Reliance-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
Rv: Riverwash-----	100	Not rated		Not rated		Not rated	
ScE: Sansarc-----	65	Very limited Slope Depth to bedrock Too clayey	1.00 1.00 1.00	Very limited Slope Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Slope Too clayey	1.00 1.00 1.00
Rock Outcrop, Soft--	30	Not rated		Not rated		Not rated	
So: Scott-----	85	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Ponding	1.00 1.00	Very limited Depth to saturated zone Ponding Too clayey	1.00 1.00 0.50
TrE: Tassel-----	70	Very limited Depth to bedrock Slope	1.00 1.00	Very limited Slope	1.00	Very limited Depth to bedrock Slope Seepage	1.00 1.00 0.50
Rock Outcrop, Sandstone-----	20	Not rated		Not rated		Not rated	
U1A: Uly-----	85	Not limited		Not limited		Not limited	

Section II
Soil and Site Information

Gregory County, South Dakota
Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
UlB: Uly-----	85	Not limited		Not limited		Not limited	
VaC: Valentine-----	85	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
VaD: Valentine-----	85	Very limited Seepage Too Sandy Slope	1.00 1.00 0.96	Very limited Seepage Slope	1.00 0.96	Very limited Too Sandy Seepage Slope	1.00 1.00 0.96
Vt: Vetal-----	90	Very limited Seepage	1.00	Very limited Seepage	1.00	Somewhat limited Seepage	0.50
W: Water (less Than 40 Acres)-----	100	Not rated		Not rated		Not rated	
Wd: Wendte-----	90	Very limited Depth to saturated zone Too clayey Flooding	1.00 0.50 0.40	Very limited Depth to saturated zone Flooding	1.00 0.40	Somewhat limited Too clayey	0.50
We: Wendte-----	90	Very limited Flooding Depth to saturated zone Too clayey	1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Somewhat limited Too clayey	0.50
Wh: Whitelake-----	90	Very limited Depth to saturated zone Too Sandy Sodium content Seepage	1.00 1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Sodium content Too Sandy Seepage	1.00 0.50 0.21

Section II
Soil and Site Information

Sanitary Facilities Table 2

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation.)

Map symbol and soil name	Pct. of map unit						
Wn: Witten-----	99	Very limited Too clayey	1.00	Not limited		Very limited Too clayey	1.00

